





An L-shaped metal bracket is shown inside a circle. To its right is a power drill with a diagonal line through it, indicating it should not be used.	A warning triangle with an exclamation mark inside.	A circular clock face with tick marks around the perimeter and two hands.
<p>30'</p>		
A rectangular block is shown on a surface with diagonal hatching. To its right is the same block with a diagonal line through it, indicating it should not be used.	A warning triangle with an exclamation mark inside.	A simple line drawing of a person standing.
<p>1</p>		



x 1




x 1




x 2

1




x 1

2




x 2

3




x 4

4




x 4

5






x 10

6






x 10

1




2




3

1




x 1

4



x 4

5



x 4

6



x 4

