






























Assembly Instruction



① X2 	② X2 	③ X1 			
④ X2 	⑤ X2 	⑥ X8 			
⑦ X2 	⑧ X2 	⑨ X2 			
⑩ X4 	⑪ X3 	⑫ X2 			
⑬ X2 	⑭ X4 	A X8  M8X40	B X4  M8X12	C X18  M6X50	
D X8  M6X40	E X2  M6X12	F X4  M6	G X10 	L X16 	


Difference screws display (1:1)



M6: Screw outer diameter 6mm
M8: Screw outer diameter 8mm


Step 1

C	M6X50	10
G		10




Step 2

A	M8X40	4
D	M6X40	2




Step 3

A	M8X40	4
D	M6X40	2




Step 4

D	M6X40	4
F	M6	4




Step 5

B	M8X12	4
---	-------	---




Step 6



Step 7


E	M6X12	2
---	-------	---




2 pieces need to be assembled.

Step 8

C	M6X50	8
---	-------	---



Step 9



Step 10

