




ASSEMBLY INSTRUCTION







Parts BOX1




① x 1




② x 1




③ x 1




⑦ x 2




⑧ x 2




⑨ x 1



⑩ x 1




⑫ x 2




⑮ x 2


Parts BOX2




④ x 1




⑤ x 1



⑥ x 1




⑬ x 2



⑯ x 2




⑰ x 2




⑱ x 1

Hardware




A

M8*20
34PCS



B

M8*40
23PCS




C

M8*60
10PCS




D

1 PC




⑪ x 2





⑭ x 6


Step 1






B M8*40 4PCS




Step 2




B M8*40 9PCS





Step 3

 **B** M8*40 6PCS  **C** M8*60 2PCS



Step 4


 **A** M8*20 12PCS



Step 5




A M8*20 14PCS



Step 6




A M8*20 8PCS




Step 7



B M8*40 4PCS






Step 8



Step 9



C M8*60 8PCS



finish

