


ASSEMBLY INSTRUCTION


METAL QUEEN BED

A Headboard




1pc

B Footboard




1pc

C Side Rail



2pcs

D Slats



3pcs

E Extension Leg




2pcs

F Support Leg



3pcs

G Bar



1pc

H Bolt (Gold)
1/4", 57mm




2pcs

I Bolt
1/4", 44mm




9pcs

J Bolt
1/4", 16mm



8pcs

K Bolt (Gold)
1/4", 16mm



4pcs

L Nut
1/4"



6pcs

M Flat Washer
ø 16mm




23pcs

N Flat Washer (Gold)
ø 16mm



6pcs

O Allen Wrench
4X4mm




1pc

P Wrench
11.3mm



1pc




This page lists all the contents included in the box. Please take the time to identify the hardware as well as the individual components to this product. As you unpack and prepare for assembly, place the contents on a carpeted or padded area to protect them from damage.


ASSEMBLY

Do not fully tighten all bolts until assembly is complete. This will help all parts to assemble properly.


- 1** Assemble the bar (G) to the extension leg (E) with 2pcs bolts (H) and 2pcs flat washer (N), then fastened using allen wrench (O).




- 2** Assemble the headboard (A) to the extension leg (E) with 4pcs bolts (K) and 4pcs flat washer (N), then fastened using allen wrench (O).



- 3** Assemble the side rail (C) to the extension leg (E) and the footboard (B) with 8pcs bolts (J), and 8pcs flat washer (M), then fastened using allen wrench (O).




- 4** Assemble the slat (D) to the support leg (F) with 1pc bolt (I) and 1pc flat washer (M) for each support leg (F), then fastened using allen wrench (O).



5

Assemble the slat (D) to the side rail (C) with 1pc bolt (I), 1pc nut (L) and 2pcs flat washer (M) for each end of slat (D), then fastened using allen wrench (O) and wrench (P).



WARNINGS:

- Use only mattress which is 79"-80" long and 59"-60" wide.
 - Do not allow horseplay or under the bed and prohibit jumping on the bed.
 - Periodically check and ensure that all the components are in their proper position, free from damage, and that all connectors are tight.
 - Do not use substitute parts, contact the store for replacement part.
 - Maximum total weight is not to exceed 600 lbs.
- **Keep these instructions for future reference.**

Cleaning & Care

Treat surface with care. Surface is resistant to scratches but is not scratch resistant. Clean surfaces with a dry or damp soft cloth. Do not use abrasive cleaners. Hardware may loosen over time. Periodically check that all connections are tight.