


Assembly Instructions




Special Warnings

- Keep your furniture out of direct sunlight. Please use desk pads and coasters to protect the surface from dents, scratches, and moisture from hot or cold liquids.
- For cleaning, wipe the surface with a damp (not wet) cloth or wipe dry with a clean lint free cotton cloth. Window cleaning liquid or a similar cleaning liquid can be used to clean glass surface.


Operation Instructions

- Please check that all parts are present before you start the assembly of your furniture. For the protection of your furniture, place all parts on a clean and smooth surface to prevent any damage.
- Please periodically check all fitting and re-tighten as necessary.
- **Please assemble the table by 2 persons or more.**
- Do NOT over tighten hardware.


①




②




③




④




⑤




⑥



⑦



⑧



⑨




⑩




⑪




⑫




⑬




⑭




⑮




⑯




⑰




⑱




⑲




⑳




㉑




㉒





㉓






24








12"




3 Hours




Part.	Item.	QTY.	
A	M5X45	26	
B		26	
C	M3.5X14	24	
D	M5X40	32	
E	M6X40	2	
F	M6	2	
G	M6X45	2	
H	M4X20	6	
I	M4X96	3	
J	M6X25	6	
K	M3X25	4	
L		4	
M		2	
			
			

5X45mm bolt installation as below




1



.SCREWS


C M3.5X14
6 PCS

2




.SCREWS

A M5X45
8 PCS




3




.SCREWS

B M5X45
4 PCS




4




.SCREWS

B  M5X45
4 PCS 




5



.SCREWS

C  M3.5X14
6 PCS 


6



.SCREWS


A  M5X45
4 PCS 

7




.SCREWS

B M5X45
4 PCS




8



.SCREWS

D M5X40
8 PCS

9



.SCREWS



K M3X25
4 PCS

.SCREWS

L 4 PCS

10




.SCREWS			
B		M5X45	
A		8 PCS	



11



.SCREWS			
B		M5X45	
A		2 PCS	

.SCREWS			
M		ø6X40	
		2 PCS	




12

.SCREWS			
B		M5X45	
A		4 PCS	




13

Option 1




.SCREWS		.SCREWS		.SCREWS	
E	M6X40	F	M6	G	M6X45
	2 PCS		2 PCS		2 PCS

Option 2




.SCREWS		.SCREWS		.SCREWS	
E	M6X40	F	M6	G	M6X45
	2 PCS		2 PCS		2 PCS

14




.SCREWS	
D	M5X40
	4 PCS

15



16




.SCREWS

D M5X40

4 PCS



17




.SCREWS

J M6X25

2 PCS




18




.SCREWS		.SCREWS	
I	1 PCS	H	M4X20 2 PCS

19




.SCREWS	
C	M3.5X14 4 PCS

20




.SCREWS	
D	M5X40 4 PCS

21



22




.SCREWS	
D	M5X40 4 PCS

23

.SCREWS

J M6X25
2 PCS





24

.SCREWS


I 1 PCS



.SCREWS

H M4X20
2 PCS






25

.SCREWS

C M3.5X14
4 PCS





26

Option 1

Option 2

