

Decal
Squeegee



Solid Adhesive Barrier

Decal


Translucent

Transfer Sheet



Step 1: Lay receptacle on a clean area, with the decal side facing outward.

RECYCLE




Step 2: Use the squeegee or your finger to peel up a corner of decal

CLe



Step 3: Pull the decal away from the surface slowly and carefully to avoid ripping and residue

RECYCL



Step 4: Repeat steps 1 and 2 for remaining parts of the decal



Step 5: If there is any residue left on the receptacle attempt to just rub it off with fingers, or use warm, soapy water and cloth