





Assembly Instruction



A	8	B	x20	C	x6	L	x1
M6x12mm		M6x25mm		M6x45mm		4mm	


1

C	x6
M6x45mm	
L	x1
4mm	




2


B	x12
M6x25mm	
L	x1
4mm	



3




B x6




M6x25mm


L x1



4mm



4




A x2




M6x12mm

B x2





M6x25mm


L x1



4mm



5



A x6




M6x12mm

L x1



4mm



TIGHT 100%

