















ASSEMBLY INSTRUCTION












PARTS

①  x1	②  x1	③  x1
④  x1	⑤  x1	⑥  x1
⑦  x1	⑧  x1	⑨  x1
⑩  x1	⑪  x1	⑫  x4
⑬  x1		







HARDWARE

Ⓐ  x12 +1(spare)	Ⓑ  x12 +1(spare)	Ⓒ  6x30mm +1(spare)	Ⓓ  x6 3x12mm +1(spare)	Ⓔ  x8 4x30mm +1(spare)
Ⓕ  x1	Ⓖ  x2	Ⓗ  x1 4x16mm	Ⓘ  x2 4x10mm	Ⓙ  x16 5x14mm +1(spare)
Ⓚ  x4				

STEP 1




STEP 2




STEP 3

	Ⓑ x 4
	Ⓒ x 4




STEP 4


	Ⓔ x 4
	Ⓒ x 4



STEP 5




STEP 6




STEP 7

	Ⓑ x 4
	Ⓒ x 4




STEP 8


	Ⓐ x 4
--	-------



STEP 9




STEP 10




STEP 11

	(B) x 4
---	---------




STEP 12

	(F) x 1
	(H) x 1




STEP 13

	Ⓢ x 2
--	-------




STEP 14

	ⓐ x 16
	Ⓚ x 4



STEP 15



STEP 16

