



















PARTS LIST

① x2 	② x1 	③ x1 
④ x1 	⑤ x2 	⑥ x1 
⑦ x1 	⑧ x1 	⑨ x1 
⑩ x1 	⑪ x1 	


HARDWARE LIST

A x4 	B x12  6*30MM	C x8  7*48MM	D x4  1/4*1-1/8MM	E x4  4*30MM
F x1  M4*20MM	G x4 	H x1 	I x2  3.5*12MM	J x1 


STEP 1




STEP 3




STEP 2




STEP 4




STEP 5




STEP 6




STEP 7



STEP 8



STEP 9



STEP 10

