



DNING TABLE

Assembly Instructions
Instructions De Assemblée
Instructions d'Assemblée

PARTS



x6



x6





x6






x6

1



2



Do not over tighten.
Do not use power tools to assemble.