







I870100576A1/A2





















Tools required
(not included)



2 people for assembly



① x1pc 	② x1pc 	③ x1pc 
④ x1pc 	⑤ x1pc 	⑥ x1pc 
⑦ x2pcs 	⑧ x2pcs 	⑨ x1pc 
⑩ x1pc 	⑪ x2pcs 	⑫ x1pc  ⑬ x1pc 



A  M6x35mm 8+2PCS	B  M6x27mm 8+2PCS	C  M6x15mm 8+2PCS	D  ST5x45mm 8+2PCS
E  M6 4+1PCS	F  ST3x12mm 2PCS	G  1PC	H  ST3.5x10mm 2PCS
I  1PC	J  ST3.5x12mm 20+2PCS	K  2PCS	L  2PCS
M  5PCS	N  4+1PCS	O  2PCS	P  2PCS
M4  1PC			

1

Cx2





Px2



3

Ax2



Dx4





4

Ax2


Dx4



5		Ax2	Cx2	Ex2
				





6		Cx2	Ex2
			





7

Bx4




8

Bx4



9


Fx2



Gx1




Mx5




10

Hx2




Ix1



11

Jx20








Kx2




Lx2



Nx4



12



13

Ox2

