







A

66PCS

B

66PCS
8*40

C

70PCS
3.5*14

D

34PCS

E

E1 E2
4PCS

F

4PCS

G

1PCS

H

2PCS
4*12

I

2PCS
6*30

J

2PCS
3.5*30

K


K1 K2
2PCS




Hardware installation demonstration

NOTE: Please make sure "A" hardware tightened and can't be pulled out!


I



II








III






IV




Scan QR code for assembly video






1



Put A on ①

A*9 D*4 E1*2







2



Put A on ②

A*9 D*4 E1*2

3




Put A on (8) (9) (10)

Put C on (3) (5) (6) (8) (9) (10)

A*12 C*34


4



Put A on (7)

A*24



5



Put A on 13

A*12


6



Put C on 11 12

C*36


7




Put B on (3) (5) (6)


B*9

8






Put B on (3) (5) (6)




Put B on 11 12

B*12





Put B on (8) (9) (10) (11) (12)

B*24







Put B on (8) (9) (10)











D*16 F*4









End