












Assembly Instructions







A  $\varnothing 15 \times 9.5 \text{MM}$ 30+5PCS	B  $\varnothing 6 \times 24 \text{MM}$ 30+5PCS	C  $\varnothing 8 \times 30 \text{MM}$ 24+4PCS
D  $\varnothing 4 \times 12 \text{MM}$ 12+2PCS	E  $\varnothing 4 \times 16 \text{MM}$ 24+4PCS	F  4PCS
H  4PCS	I  2PCS	


1



2




3




	A*4PCS		C*2PCS
--	--------	---	--------

4




	B*8PCS
--	--------

5




	A*8PCS		C*8PCS
--	--------	---	--------

6




	B*12PCS
--	---------

7




	A*6PCS		C*6PCS
--	--------	--	--------

8




	A*6PCS		C*6PCS
---	--------	---	--------

9





	A*4PCS		B*4PCS		F*4PCS
---	--------	---	--------	---	--------

10







	E*24PCS		H*4PCS
---	---------	---	--------

I is first split into I1, I2, I3, as shown below right.



X2



	D*12PCS		I*2PCS
---	---------	---	--------