





















USER'S MANUAL





























Parts List








- 1 
2PCS
- 2 
1PC
- 3 
1PC
- 4 
2PCS
- 5 
1PC
- 6 
1PC
- 7 
1PC
- 8 
1PC
- 9 
1PC
- 10 
1PC
- 11 
1PC
- 12 
1PC
- 13 
1SET
- 14 
2PCS
- 15 
1PC
- 16 
1PC





Hardware List

| | | | |
|---|--|---|--|
| <p>A</p> <p>$\phi 3*12$</p>  <p>2PCS</p> | <p>B</p> <p>$\phi 6*32$</p>  <p>20PCS</p> | <p>C</p> <p>M6x15mm</p>  <p>10PCS</p> | <p>D</p> <p>M6x25mm</p>  <p>4PCS</p> |
| <p>E</p> <p>M6x45mm</p>  <p>4PCS</p> | <p>F</p> <p>M6x50mm</p>  <p>4PCS</p> | <p>G</p> <p>$\phi 8$</p>  <p>24PCS</p> | <p>H</p> <p>M8x50mm</p>  <p>8PCS</p> |
| <p>I</p> <p>M8</p>  <p>8PCS</p> |  <p>1PC</p> |  <p>1PC</p> |  <p>1PC</p> |














| | |
|---|------|
|  | |
| M6x50mm | |
| F | 4PCS |
|  | |
| Ø8 | |
| G | 4PCS |
|  | |
|  | |






Please don't tighten the screws completely .










| | |
|---|------|
|  | |
| M6x45mm | |
| E | 4PCS |
|  | |
| M6x25mm | |
| D | 4PCS |
|  | |
| Ø8 | |
| G | 4PCS |
|  | |
|  | |


Please tighten all screws at the end of each screw alignment.











| | |
|---|---|
|  |  |
| M8x50mm | |
| H | 4PCS |
|  |  |
| ø8 | |
| G | 8PCS |
|  | |
| M8 | |
| I | 4PCS |




| | |
|---|------|
|  | |
| M8x50mm | |
| H | 4PCS |



| | |
|---|------|
|  | |
| ø8 | |
| G | 8PCS |



| | |
|---|------|
|  | |
| M8 | |
| I | 4PCS |

