



Assembly Instructions




NO.	QTY.	LINEDRAWING
A	16	
B	2	
C	3	
D	2	
E	18	
F	4	
G	4	$\phi 6*60$
H	4	$\phi 3.5*30$
I	12	$\phi 3.5*14$
J	12	$\phi 3*14$
K	16	$\phi 20$




NO.	QTY.
①	1
②	1
③	1
④	1
⑤	1
⑥	1
⑦	2
⑧	2
⑨	1
⑩	1
⑪	1
⑫	1

1




A*6

2




3




A*6+E*2

4




5



A*4


6






B*2+I*12

7


1483mm




D*2+F*4+G*4+H*4




8



E*16




9



C*3+J*12

10



K*16