






Assembly Instruction




 
Hammer and Screwdriver
are not included !!




NO.	QTY.	LINEDRAWING
(A)	33	
(B)	33	 Ø15
(C)	22	 Ø8x40
(D)	2	 Ø5x40
(E)	4	
(F)	4	
(G)	64	 Ø3.5x14
(H)	1	
(I)	1	
(J)	33	
(K)	4	
(L)	2	
(M)	8	
(N)	2	  3.5*35  3.5*14 

PARTS LIST



NO.	QTY.
①	1
②	1
③	1
④	1
⑤	1
⑥	1
⑦	1
⑧	1
⑨	4
⑩	1
⑪	1
⑫	2
⑬	1
⑭	1
⑮	1
⑯	1
⑰	1

1




H

1x

G

4x


2



I

1x

3



A

2x


B

2x

J

2x

4



A

1x

B

1x

J

1x

1

H

1x

G

4x

2

I

1x

3

A

2x

B

2x

J

2x

4

A

1x



B

1x


J

1x


5



6




7




A  8x	B  Ø15 8x
C  Ø8x40 6x	J  8x

8




A  8x	B  Ø15 8x
C  Ø8x40 6x	J  8x

9




A		B	 Ø15
	4x		4x
C	 Ø8x40	J	
	2x		4x

10




A		B	 Ø15
	4x		4x
C	 Ø8x40	J	
	2x		4x

11




12




L		G	
	2x		4x

13




A	B
	
6x	6x
C	J
	
6x	6x

14




E	F	G	K
			
2x	2x	12x	2x

15



K	F	G	K
			
2x	4x	12x	2x


16



G

16x


17




G

16x

19



18



M

8x

N

2x