










































Frame Assembly Diagram



D41" H5.23" L18

Parts Number	part	picture	Description	Qty
	ZB(P07)		Ground wire	1
	ZC		Junction Caps	3
	ZD(P01)		Mounting bracket(L7.5"*W7.5")	1
	ZE(P11)		Canopy(ϕ 7.9"H1",Chrome)	1
	ZF(P15)		M6 Knurled nut	4
	ZG		Mounting bracket screw	2
	P02		Washer	4
	P03		M6 Hex nut	4
	P04		M4 Lock washer	2
	P05		Ground screw	1
	P06		M10 Hex nut	4
	P08		M10 Lock washer	4
	P09		M10 Nipple (L0.6")	2
	P10		M10 Rubber gasket	2
	P12		Cable adjustment bolt	4
	P13		Power wire adjustment bolt	2
	P14		L122" Steel cope	4
	P16		Iron crystal frame body with crystal (ϕ 8.1"H1.9")	1
	P22		Round stainless steel plate (ϕ 7.9"T0.039")	1
	P28		Wire rope clamp	8
	P29		M4 Nipple	32
	P30		M4 Phillip flange bolt (L0.3")	13
	P31		M4 Phillip flange bolt (L1")	4
	P33		M4 Hex nut	5
	P17		Pipe ring body(ϕ 35.6"H0.6")	1
	P18		M10 Nipple(L0.4")	18
	P19		Coupling(ϕ 0.6"H0.4")	18
	P20		Iron coupling(L0.5"W0.5"H0.4")	18
	P21		Socket (ϕ 0.9"H1.7",Chrome,Iron)	18
	P23		G9 Socket	18
	P25		Metal crystal frame body with crystal (ϕ 41"H7.1")	1

P26		Two holes steel bracket B(L3.3"W1.1")	3
P27		Two holes steel bracket B(L3.3"W1.1")	1
P32		Plastic washer	2
P34		Heat shrink tubing	8
P35		Junction caps	8
P36		Cable tie	8
P37		Clear Round Electrical Wire (L137.8",18#, Clear)	1
P38		Cable buckle	2
P39		Allen key	1