



















Hardware

		 Ø8*40	 M7*50	 M3.5*14
A*26	B*26	C*10	D*8	E*8
 M3.5*12	 M4*35	 M4*16	 M3*14	 M3*12
F*4	G*8	H*3	I*32	J*8
 M5*40		 M1 M2	 Ø6*30	 Ø20
K*4	L*2	M*2	N*8	O*28
 M6*12	 M6*35	 M4*16	 S1 S2	
P*16	Q*4	R*4	S*2	T*2
				
U*2	V*1	W*1	X*2	Y*1

Parts list




1




A*8	C*4
	 Ø8*40

2





M1



A*8	C*2	I*12	M1*2
	 Ø8*40	 M3*14	


3



B*4





4



B*4






5




A*6	C*2
	
	Ø8*40


6




I*16	S2*2	V*1
		
M3*14		

7




R*4	W*1
 M4*16	

8




B*6


9



C*2	N*4
	
Ø8*40	Ø6*30


10



K*4

M5*40


11



B*8



12



I*4




M3*14


S1*2




13



14





15




F*4	L*2
	
M3.5*12	

16




E*8	H*1
	
M3.5*14	M4*16

17




A*4	N*4
	
	Ø6*30

18




B*4	G*8	H*2
		
	M4*35	M4*16

19



J*8	M2*2
 M3*12	


20




O*28




21



22



23



24

