



Assembly Instruction




Hammer and Screwdriver
are not included !!

NO.	QTY.	LINEDRAWING
(A)	34	
(B)	34	
(C)	32	
(D)	24	
(E)	16	
(F)	16	
(G)	8	
(H)	12	
(I)	8	

Assembly Instruction




1




	D	
	8x	8x

2




	A	
	8x	8x
	B	
	8x	8x
	C	
	6x	6x

3




	A	
	14x	14x

4



	B	
	14x	14x
	C	
	10x	10x


5



X2



A	B	C	H
6x	6x	4x	6x

6




C
8x

7





E
16x

8




D
16x

9



I		8x
F		16x

10



G		
		8x

