





ASSEMBLY INSTRUCTIONS




PARTS

check that you've received
all parts listed below

BOX:1/2

① (1PC)



② (1PC)



⑫ (6PCS)



⑪ (4PCS)



⑨ (2PCS)



⑩ (2PCS)



⑭ (4PCS)






HARDWARE



PARTS

check that you've received
all parts listed below

BOX:2/2




③ (2PCS) 	⑬ (1PC) 
④ (1PCS) 	⑤ (1PC) 
⑥ (1PC) 	⑦ (1PC) 
⑧ (2PCS) 	

move from
page 3

HARDWARE

check that you've received
all parts listed below

Hardware List

NO	OUTLOOK	DESC	QTY
A		Bolts Ø $\frac{5}{16}$ " x 20 mm	18 pcs
B		Bolts Ø $\frac{5}{16}$ " x 50 mm	16 pcs
C		Plain washer Ø19x1.5 mm	34 pcs
D		Spring washer Ø13x1 mm	34 pcs
E		Allen key 80x30x4 mm	1 pc
F		Screws Ø4x30 mm	26 pcs



add 4 words
14-18(B-C-D)




add 4 words
30-34(B-C-D)



STEP 1




STEP 2




STEP 3

Bx4  Ø 7/8" x 50 mm	Cx4 	Dx4 	Ex1 	
--	--	--	--	--




STEP 4

Ax4  Ø 7/8" x 20 mm	Cx4 	Dx4 	Ex1 	
--	--	--	--	--




STEP 5

Ax6  Ø 5/16" x 20 mm	Cx6 	Dx6 	Ex1 	
---	--	--	--	--




STEP 6

Bx4  Ø 5/16" x 50 mm	Fx8  8 pcs	Cx4 	Dx4 	Ex1 
---	---	--	--	--




STEP 7

Fx18  18 pcs	
---	--




STEP 8

Bx4  Ø 5/16" x 20 mm	Cx4 	Dx4 	Ex1 	
---	--	--	--	--



STEP 9

Bx4  Ø 16" x 50 mm	Cx4 	Dx4 	Ex1 	
--	---	---	---	--



finish

