

1.




Diagram 1 shows an L-shaped bracket (1) with pre-drilled holes. A callout shows four screws (2) and four washers (2) to be used for assembly.

2.




Diagram 2 shows the bracket (1) with hardware (2) installed. A callout shows hardware (A) and a wrench icon, indicating that hardware (A) is required for the next step.

3.




Diagram 3 shows the bracket (1) being flipped over, indicated by a red curved arrow, to install hardware (2) on the bottom flange.




Diagram 4 shows the final assembly with hardware (2) installed on both the top and bottom flanges of the bracket (1).