





Assembly Instructions




29



- | | | | | | |
|----------|---|--------|----------|---|--------|
| E |  | [×8] | Q |  | [×2] |
| F |  | [×8] | | | |




×139



(A)

34mm

×123



(B)

Ø15*12mm


×76



(C)

Ø8*30mm


×16



(D)

Ø15*10mm


×8



(E)


Ø3*18mm

×8



(F)


×6



(G)

孔距128mm

×4



(H)


M4*22mm

×7



(J)


×14



(K)

Ø4*15mm


×16



(L)

Ø5*38mm


×2




(M)


30*17*17mm

28





27





(R)  [×16]

×4
(N)  14"
350*27mm


×4
(P)  4"
113*42mm

×2
(Q) 

×42
(R)  Ø3.5*12mm

×4
(T)  13*Ø8*25mm

×8
(S)  M4*16mm


×2
(V)  L42*W16*1.5mm

×2
(W)  4mm
4mm*24*70


×48
(U)  Ø3.5*11mm


1


Please fasten the screws through these holes for this step




Please fasten the screws through these holes for this step




(A)  [×26]


(N)  [×4]

(M)  [×1]


(R)  [×2]

(U)  Ø3.5*11mm [×12]


26




× 2





× 2




(G)  [×2]

(H)  [×4]


(P)  4'' [×4]

(R)  [×16]


25





× 4




× 4




- | | |
|--|--|
| A  [×16] | D  [×16] |
| G  [×4] | S  [×8] |



2





× 2





× 2



× 2

- | | |
|--|--|
| A  [×12] | C  [×24] |
| J  [×4] | K  [×8] |

3




B




[x12]

24




N




[x8]

L




[x16]


U





[x24]


23




- T  [×4]
 W  [×2]

4



- A  [×4]
 B  [×4]
- C  [×16]

5




B



[×10]

22




C



[×9]

21




C




[×9]

6



7




B



[×10]

20




C



[×3]

19





C



[×6]

8




B




[×6]

R




[×1]




9

Please fasten the screws through these holes for this step



Please fasten the screws through these holes for this step



(A) [×26]



(N) [×4]

(M) [×1]

(R) [×2]

(U) Ø3.5*11mm [×12]

18





(A) [×6]

(C) [×6]


(C) [×3]

17




A  [×24] **C**  [×16]

10





B  [×10]

11



16




B




[×12]

V





[×2]

S



[×4]

15





B



[×13]

12







B





[×10]



13



- B  [×6]
 R  [×1]

14



- A  [×25]
 C  [×14]
- J  [×3]
 K  [×6]