



/

















Make sure the arrow on the screw align to the hole on the side.























·	
14	27 25 X2 X2 X2 X2 X2 X2 X2 X2 X2 X2
H*1	]put H on board 29
► L*2	put L on board 29
X2*4	put X2 on board2526
, ,	

`	
15	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
H*1	put H on board 30
► L*2	put L on board 30
X2*4	put X2 on board2526



×	
17	2 3 4 4 4 4 4 4 4 4 4 4 4 4 4
I*1	put I on board 23
► L*2	put L on board 23
SD X2*4	put X2 on board 1920
,	

18		X2 X2 X2 X2 X2 X2 X2 X2 X2 X2 X2 X2 X2 X
	J*1	put J on board 24
<b>~</b>	L*2	put L on board 24
	X2*4	put X2 on board(1920











