







mm
inch




Ax4




Bx4




Cx4




Dx4



Ex4



Fx4



① x44




M6x $\frac{14}{0.6}$

② x2




4x60
0.2x2.4

③ x24





M6x $\frac{25}{1.0}$

④ x20






M6x $\frac{35}{1.4}$

1






2



80% ✓



100% ✗







80% ✓







100% ✗





3




4



5



80%



6

