

Assembly Instructions







Hardware List

(0) Ø6x12mm Α 16 pcs **Bolt** Rubber bumper 8 pcs В Ø15mm С M 4 Wrench рс D Wrench рс

The hardware quantities listed above are required for proper assembly. Some extra hardware may also have been included.




Use wrench (C) to secure shelf frame (3) to leg (4) with bolt (A).




Use wrench (C) to secure top frame (1) to leg (4) with bolt (A).

Step 3




Screw caster (5,6) to leg (4), then tighten with wrench (D).

Step 4




Place rubber bumper (B) as per diagram.





Place glass shelf (2) on top of the shelf frame (3) carefully.

Step 6



Final Assembly