











Ax2 	Bx1 	Cx4 	Dx4 	Ex4 
Fx8  M8x $\frac{40}{1.6}$	Gx32  M6x $\frac{15}{0.6}$	Hx8  M8	Lx32  M6	Mx1  M8
Nx1  M6	Ox2 	Px2 	 mm inch x1	




1






2



3



4



5

