
















INSTRUCTION MANUAL




PC002-1012Br

A		4	L		4
B		2	M6		4
B1		2	M7		2
C		2	M8		6
C1		2	M9		4
D		6	P		4
E		4	Q		72
F		4	X	 M6*10	32
F1		4	X1	 M6*15	85
G		4	X2	 5*10	52
G1		4	Y1		4
G2		2	Y2		4
H		4	Y3		4
H1		4	Y4		4
H2		2	Y5		4
J1		4	Z		1
J2		4	Z1		1
K		1	Z3		8
K1		1			8
					1


step1




step2




step3




step4




step5




step6




step7




step8




step9




step10




step11




step12




step13




step14




step15




step16




step17




step18






step19





step20



step21



step22



or

