





An icon showing an L-shaped metal bracket inside a circle, and a power drill with a diagonal line through it, indicating that a power drill should not be used for assembly.	A warning triangle icon with an exclamation mark inside.	A clock icon showing the time as approximately 1:50.
An icon showing a rectangular cushion on a textured surface inside a circle, and a screwdriver with a diagonal line through it, indicating that a screwdriver should not be used for assembly.	A warning triangle icon with an exclamation mark inside.	A simple icon of a person standing.

15'

1



<b>A</b>	<b>B</b>	<b>C</b>	<b>D</b>
			
<b>x 1</b>	<b>x 2</b>	<b>x 2</b>	<b>x 1</b>




**C x 2**




**B x 2**




**A**







**D**






**E x 4**





<b>E</b>	<b>F</b>	<b>G</b>	<b>H</b>
		 M6 x 24	
<b>x 4</b>	<b>x 8</b>	<b>x 8</b>	<b>x 1</b>

1



2



3

