




Assembly Guide | Cube Storage

Parts List

 Panels - A	 Feet - B	 Connectors - C	 Tools - Hammer
---	---	---	---


Step 1



A x 1
C x 4


Make sure the connector is mounted with the correct orientation.

Step 2




A
B
A

Step 3




A x 5
C x 3

Step 4




A
A
A x 2
C x 3

Step 5



A x 5
C x 3

Step 6



A
A
A x 2
C x 3