









ASSEMBLY INSTRUCTION






Part list


A		1 PC x2
B		1 PC x2
C		1 PC x2
D		2 PCS x2
E		1 PC x2
F		1 PC x2

Hardware list

①	 M6 x 50	2 PCS x2
②	 M6 x 40	2 PCS x2
③	 M6 x 30	8 PCS x2
④	 M6 x 35	4 PCS x2
⑤	 Eru M6	4 PCS x2
⑥	 W6 x 16 x 1	16 PCS x2
⑦	 M4	1 PC
⑧	 M10	1 PC
⑨		4 PCS x2


STEP 1

① x 2	⑤ x 2	⑥ x 4	⑦ x 1	⑧ x 1
				
M6x50	M6	W6x16x1	M4	M10




STEP 2

② x 2	③ x 8	⑤ x 2	⑥ x 12	⑦ x 1	⑧ x 1
					
M6x40	M6x30	M6	W6x16x1	M4	M10




STEP 3


④ x 4	⑦ x 1	⑨ x 4
		
M6x35	M4	



STEP 4



1. 50% Tighten before fixing all screws, Allen wrench is recommended instead of an electric drill.
2. Place the item on a flat ground to adjust and make sure it remains stable.
3. Tighten up all screws with tools gradually.
4. If the screws are not aligned with holes during assembly, please loosen all the other screws to 50% and continue the assembly process.
5. If the item is not stable, please loosen all the screws, adjust it on a flat ground and tighten up all screws again.
6. Note: If one or some screws are fully tightened during assembly, chances are the others will not be aligned with holes. In addition, all the holes are designed to be relatively larger to provide more space for the adjustment of the screws.



Part list

G		1 PC x2
H		1 PC x2
I		1 PC x2
J		1 PC x2
D		1 PC x2

Part list



E		1 PC x2
F		1 PC x2
K		1 PC x2

Hardware list

①	 M6 x 50	6 PCS x2
②	 M6 x 40	2 PCS x2
③	 M6 x 30	5 PCS x2
④	 M6 x 35	4 PCS x2
⑤	 Eru M6	8 PCS x2
⑥	 W6 x 16 x 1	21 PCS x2
⑦	 M4	1 PC
⑧	 M10	1 PC
⑨	 	4 PCS x2




STEP 5

① x 6	⑤ x 6	⑥ x 12	⑦ x 1	⑧ x 1
				
M6x50	M6	W6x16x1	M4	M10





STEP 6

② x 2	③ x 5	⑤ x 2	⑥ x 9	⑦ x 1	⑧ x 1
					
M6x40	M6x30	M6	W6x16x1	M4	M10




STEP 7


④ x 4	⑦ x 1	⑨ x 4
		
M6x35	M4	







STEP 8




1. 50% Tighten before fixing all screws, Allen wrench is recommended instead of an electric drill.
2. Place the item on a flat ground to adjust and make sure it remains stable.
3. Tighten up all screws with tools gradually.
4. If the screws are not aligned with holes during assembly, please loosen all the other screws to 50% and continue the assembly process.
5. If the item is not stable, please loosen all the screws, adjust it on a flat ground and tighten up all screws again.
6. Note: If one or some screws are fully tightened during assembly, chances are the others will not be aligned with holes. In addition, all the holes are designed to be relatively larger to provide more space for the adjustment of the screws.



Part list



L		1 PC x2
C		2 PCS x2
M		2 PCS x2
E		1 PC x2

Hardware list

③	 M6 x 30	12 PCS x2
④	 M6 x 35	4 PCS x2
⑥	 W6 x 16 x 1	12 PCS x2
⑦	 M4	1 PC
⑨		4 PCS x2



STEP 9

③ x 2	⑥ x 2	⑦ x 1
		
M6x30	W6x16x1	M4





STEP 10

③ x 10	⑥ x 10	⑦ x 1
		
M6x30	W6x16x1	M4




STEP 11


④ x 4	⑦ x 1	⑨ x 4
		
M6x35	M4	






STEP 12





1. 50% Tighten before fixing all screws, Allen wrench is recommended instead of an electric drill.
2. Place the item on a flat ground to adjust and make sure it remains stable.
3. Tighten up all screws with tools gradually.
4. If the screws are not aligned with holes during assembly, please loosen all the other screws to 50% and continue the assembly process.
5. If the item is not stable, please loosen all the screws, adjust it on a flat ground and tighten up all screws again.
6. Note: If one or some screws are fully tightened during assembly, chances are the others will not be aligned with holes. In addition, all the holes are designed to be relatively larger to provide more space for the adjustment of the screws.





Part list

N		1 PC
O		2 PCS
P		2 PCS



Hardware list

③	 M6 x 30	12 PCS
④	 M6 x 35	4 PCS
⑥	 W6 x 16 x 1	12 PCS
⑦	 M4	1 PC
⑨		4 PCS



STEP 13




STEP 14



STEP 15



STEP 16



1. 50% Tighten before fixing all screws, Allen wrench is recommended instead of an electric drill.
2. Place the item on a flat ground to adjust and make sure it remains stable.
3. Tighten up all screws with tools gradually.
4. If the screws are not aligned with holes during assembly, please loosen all the other screws to 50% and continue the assembly process.
5. If the item is not stable, please loosen all the screws, adjust it on a flat ground and tighten up all screws again.
6. Note: If one or some screws are fully tightened during assembly, chances are the others will not be aligned with holes. In addition, all the holes are designed to be relatively larger to provide more space for the adjustment of the screws.

FINISH

