


Diagram illustrating assembly steps and safety warnings:


- Step 1:** Shows an L-shaped metal bracket and a power drill with a slash through it, indicating that a power drill should not be used. A warning triangle with an exclamation mark is positioned to the right.
- Step 2:** Shows a rectangular block being placed on a textured surface and another block being secured with a screw. A warning triangle with an exclamation mark is positioned to the right.
- Time:** A clock icon is shown next to the text "20'", indicating a 20-minute assembly time.
- Person:** A stick figure icon is shown next to the number "1", indicating that one person is required for assembly.

A




x 1


B



x 1




A




B

C




x 4

D



x 4

E



x 1

1

