

















ASSEMBLY INSTRUCTIONS






+SpareX2 A I x44 	+SpareX2 B I x44  01S-12mm	+SpareX2 C I x60  07.a-30mm	+SpareX2 D I x66  4*14rnm	+SpareX1 E I x5  M6*45mm	+SpareX2 F I x26  Mlr15mm
+SpareX2 G I x18  011r1.5mm	H I x4  eo-2Cr2mm	+SpareX1 I I x17 	+SpareX1 J I x 17 	+SpareX1 K x5  M6*9.S-10.5 mm	+SpareX1 L I x5  M8*25mm
M I x1  5mm	N I x1  4mm	O I x1 			

1




A	x30	B	x30	C	x36	D	x8	I	x2	J	x2	O	x1
													
Ø7*35mm		Ø15*12mm		Ø7.8*30mm		4*14mm							

2




N	x1	H	x4	F	x8
					
4mm		60*20*2mm		M8*15mm	


3



4




5




A	x12	B	x12	C	x20	D	x56	I	x14	J	x14	O	x1
Ø7x35mm		Ø15x12mm		Ø7.8x30mm		4x14mm							

6




E	x4	K	x4	N	x1
M6x45mm		M6x9.5x10.5mm		4mm	

7




8




N	x1	G	x16	F	x16
					
4mm		Ø16*1.5mm		M6*15mm	

9



10



11

