







# Product Usage Instructions



**NO JUMPING**




# INSTALLATION GUIDE




Suggest using electric tools for installation

---


SKU:16032














SKU:16033




SKU:16034








|   |                                                                                              |         |   |                                                                                                  |        |
|---|----------------------------------------------------------------------------------------------|---------|---|--------------------------------------------------------------------------------------------------|--------|
| A |             | 65 PCS  | J | <br>J-1 J-2    | 2 PCS  |
| B | <br>M15     | 65 PCS  | T | <br>T00L      | 1 PCS  |
| C | <br>80*80   | 6 PCS   | K |               | 12 PCS |
| E | <br>M4*30   | 25 PCS  | L |               | 8 PCS  |
| D | <br>M8*40   | 13 PCS  | O | <br>O-1 O-2   | 2 PCS  |
| F | <br>M3.5*14 | 130 PCS | P |              | 1 PCS  |
| H | <br>M4*18 | 4 PCS   | Q |             | 6 PCS  |
| I |           | 4 PCS   | R | <br>M6*13   | 25 PCS |
| S | <br>M6*18 | 8 PCS   | X | <br>M15*150 | 4 PCS  |
| Z |           | 2 PCS   | M | <br>M50     | 1 PCS  |

## Special hardware install instructions





# Special hardware removal instructions




|   |                                                                                          |       |   |                                                                                           |       |
|---|------------------------------------------------------------------------------------------|-------|---|-------------------------------------------------------------------------------------------|-------|
| A |          | 8 PCS | B | <br>M15 | 8 PCS |
| M | <br>M50 | 1 PCS |   |                                                                                           |       |



# STEP 1




|   |                                                                                     |       |   |                                                                                              |       |
|---|-------------------------------------------------------------------------------------|-------|---|----------------------------------------------------------------------------------------------|-------|
| A |  | 8 PCS | B | <br>M15 | 8 PCS |
|---|-------------------------------------------------------------------------------------|-------|---|----------------------------------------------------------------------------------------------|-------|



# STEP 2




|   |                                                                                          |       |   |                                                                                    |       |
|---|------------------------------------------------------------------------------------------|-------|---|------------------------------------------------------------------------------------|-------|
| A |          | 8 PCS | D |  | 4 PCS |
| B | <br>M15 | 8 PCS |   |                                                                                    |       |


### STEP 3




|   |                                                                                              |        |   |                                                                                                  |       |
|---|----------------------------------------------------------------------------------------------|--------|---|--------------------------------------------------------------------------------------------------|-------|
| P |           | 1 PCS  | F | <br>M3.5*14 | 2 PCS |
| C | <br>80*80 | 2 PCS  | R | <br>M6*13   | 8 PCS |
| A |           | 10 PCS | D |             | 4 PCS |



### STEP 4




|   |                                                                                  |       |   |                                                                                           |        |
|---|----------------------------------------------------------------------------------|-------|---|-------------------------------------------------------------------------------------------|--------|
| A |  | 4 PCS | B | <br>M15 | 14 PCS |
|---|----------------------------------------------------------------------------------|-------|---|-------------------------------------------------------------------------------------------|--------|


STEP 5






|   |                                                                                                |       |   |                                                                                              |       |
|---|------------------------------------------------------------------------------------------------|-------|---|----------------------------------------------------------------------------------------------|-------|
| F | <br>M3.5*14 | 10PCS | O | <br>O-1 | 2 PCS |
|---|------------------------------------------------------------------------------------------------|-------|---|----------------------------------------------------------------------------------------------|-------|


|   |                                                                                     |       |
|---|-------------------------------------------------------------------------------------|-------|
| Q |  | 6 PCS |
|---|-------------------------------------------------------------------------------------|-------|


STEP 6







|   |                                                                                              |        |   |                                                                                            |        |
|---|----------------------------------------------------------------------------------------------|--------|---|--------------------------------------------------------------------------------------------|--------|
| A |              | 10 PCS | B | <br>M15  | 10 PCS |
| F | <br>M3.5*14 | 8 PCS  | O | <br>O-2 | 2 PCS  |
| D |             | 4 PCS  | J | <br>J-2 | 2 PCS  |






|   |                                                                                                |       |   |                                                                                              |       |
|---|------------------------------------------------------------------------------------------------|-------|---|----------------------------------------------------------------------------------------------|-------|
| A |             | 2 PCS | B | <br>M15 | 2 PCS |
| F | <br>M3.5*14 | 6 PCS | K |         | 3 PCS |




|   |                                                                                  |       |   |                                                                                           |       |
|---|----------------------------------------------------------------------------------|-------|---|-------------------------------------------------------------------------------------------|-------|
| A |  | 6 PCS | B | <br>M15 | 6 PCS |
|---|----------------------------------------------------------------------------------|-------|---|-------------------------------------------------------------------------------------------|-------|


STEP 9




|   |                                                                                                |       |   |                                                                                              |       |
|---|------------------------------------------------------------------------------------------------|-------|---|----------------------------------------------------------------------------------------------|-------|
| A |             | 2 PCS | B | <br>M15 | 2 PCS |
| F | <br>M3.5*14 | 6 PCS | K |         | 3 PCS |


STEP 10




|   |                                                                                  |       |   |                                                                                           |       |
|---|----------------------------------------------------------------------------------|-------|---|-------------------------------------------------------------------------------------------|-------|
| A |  | 6 PCS | B | <br>M15 | 6 PCS |
|---|----------------------------------------------------------------------------------|-------|---|-------------------------------------------------------------------------------------------|-------|

STEP 11




|   |                                                                                                |        |   |                                                                                       |       |
|---|------------------------------------------------------------------------------------------------|--------|---|---------------------------------------------------------------------------------------|-------|
| E | <br>M4*30   | 8 PCS  | K |  | 6 PCS |
| F | <br>M3.5*14 | 12 PCS |   |                                                                                       |       |

STEP 12




E




M4\*30

8 PCS

## STEP 13




E




M4\*30

8 PCS


## STEP 14




The direction of the red arrow is forward


|   |                                                                                            |       |   |                                                                                        |       |
|---|--------------------------------------------------------------------------------------------|-------|---|----------------------------------------------------------------------------------------|-------|
| H | <br>M4*20   | 2 PCS | I | <br> | 2 PCS |
| S | <br>M6*18 | 8 PCS |   |                                                                                        |       |

# STEP 15



|   |                                                                                              |       |   |                                                                                                |       |
|---|----------------------------------------------------------------------------------------------|-------|---|------------------------------------------------------------------------------------------------|-------|
| H | <br>M4*20 | 2 PCS | I | <br>      | 2 PCS |
| C | <br>80*80 | 2 PCS | R | <br>M6*13 | 8 PCS |

# STEP 16



C



80\*80

2 PCS


R





M6\*13

8 PCS




## STEP 17





## STEP 18





STEP 19




|   |                                                                                           |        |   |                                                                                    |       |
|---|-------------------------------------------------------------------------------------------|--------|---|------------------------------------------------------------------------------------|-------|
| F |  M3.5*14   | 80 PCS | L |  | 8 PCS |
| X |  M15*150 | 4 PCS  |   |                                                                                    |       |

# STEP 20



|   |                                                                                             |       |   |                                                                                           |       |
|---|---------------------------------------------------------------------------------------------|-------|---|-------------------------------------------------------------------------------------------|-------|
| F |  M3.5*14 | 4 PCS | J |  J-1 | 2 PCS |
| Z |          | 2 PCS |   |                                                                                           |       |

# STEP 21





## STEP 22

