













H  44PCS	I 3*12  44PCS	J  2SET	K  26PCS			
A  70SET	B 8*40  26PCS	C 7*50  17PCS	D 8*70  6PCS	E 3.5*14  8PCS	F  4PCS	G  8PCS




Hardware installation demonstration

NOTE: Please make sure "A" hardware tightened and can't be pulled out!


I




II



III




1






A*4 B*2 C*3

2





A*4 C*3 D*2

3




A*4 C*3 D*2




A*8 B*2 D*2

5





6




A*6


7








10




A*8




A*2 B*2 C*4


12



13




A*8 B*4




A*8 B*4

15





A*2 B*2 C*4

16







A*10 B*10 E*8 F*4





H*44 I*44

19



J*2