












Installation instruction

Please don't tighten the screws completely and go back later for a final tightening of all the screws after pieces are aligned with each other.









MADE IN CHINA

Parts List




| | | | |
|--|---|--|---|
|  <p>1</p> <p>1 pc</p> |  <p>2</p> <p>1 pc</p> |  <p>3</p> <p>2 pcs</p> |  <p>4</p> <p>2 pcs</p> |
|  <p>5</p> <p>2 pcs</p> |  <p>6</p> <p>2 pcs</p> |  <p>7</p> <p>2 pcs</p> |  <p>8</p> <p>2 pcs</p> |

Hardware List

| A | B | C | D | E |
|---|--|--|---|--|
|  <p>Ø15x12mm</p> |  <p>M6x40mm</p> |  <p>M6x30mm</p> |  |  <p>M4</p> |
| 56 pcs | 56 pcs | 8 pcs | 8 pcs | 1 pc |





1



x2

8 x2 pcs


2




8 x2 pcs

7 x2 pcs

3





4




P-05

5



4 x2 pcs


6




3 x2 pcs

4 x2 pcs

7





B



M6x40mm
12 pcs

① x1 pc

8




A





Ø15x12mm
12 pcs

① x1 pc
③ x2 pcs
④ x2 pcs


9





| B | D |
|---|---|
|  |  |
| M6x40mm | |
| 16 pcs | 8 pcs |

- 5 x2 pcs
- 6 x2 pcs



10




| A |
|--|
|  |
| Ø15x12mm |
| 4 pcs |
| C |
|  |
| M6x30mm |
| 2 pcs |

- 3 x1 pc
- 4 x2 pcs
- 5 x1 pc
- 6 x1 pc



11


| |
|---|
| A |
|  |
| Ø15x12mm |
| 4 pcs |
| C |
|  |
| M6x30mm |
| 2 pcs |



- 7 x1 pc
- 2 x1 pc
- 5 x1 pc
- 6 x1 pc

12

| |
|---|
| A |
|  |
| Ø15x12mm |
| 8 pcs |
| C |
|  |
| M6x30mm |
| 4 pcs |



- 2 x1 pc
- 3 x1 pc
- 4 x2 pcs
- 5 x1 pc
- 6 x1 pc
- 7 x1 pc

