





5




6




3



4




1



① X8

⑥ X8








2




① X4

③ X4

PART

A  X4	B  X1	C  X1
D  X2	E  X2	F  X1
G  X1	H  X1	I  X1
J  X1	K  X2	L  X2
1  M6x35 12PCS	5  M4X14 8PCS	
2  M6x30 12PCS	6  8PCS	
3  M6x55 4PCS	7  1SET	
4  M6x12 8PCS		



IMPORTANT: DON' T FASTEN BOLTS UNTIL ALL PARTS IN POSITION.