






Parts




① x 1




② x 1




③ x 1




④ x 1




⑤ x 1




⑥ x 1



⑦ x 4



⑧ x 1




⑨ x 1



⑩ x 1




⑪ x 1




⑫ x 1



⑬ x 1




⑭ x 1




⑮ x 1



⑯ x 2




⑰ x 1




⑱ x 1

Hardware




M8x20mm

Ⓐ x22pcs




M8x30mm

Ⓑ x16pcs




M8x40mm

Ⓒ x11pcs



M8x50mm

Ⓓ x1pc



M4x25mm


Ⓔ x2pc




Ⓕ x2pcs



Ⓖ x2pcs




Ⓗ x 2pc




M8 ALLEN KEY


Ⓘ x1pc

step 1




B	X4PCS	C	X4PCS
			
M8X30MM		M8X40MM	


step 2




B	X12PCS
	
M8X30MM	

step 3




A	X8PCS
	
M8X20MM	

step 4




A	X8PCS
	
M8X20MM	


step 5




C	X1PC
	
M8X40MM	

step 6




A	X6PCS
	
M8X20MM	

step 7



C	X2PCS
	
M8X40MM	

step 8



C	X4PCS
	
M8X40MM	

step 9

