












Diagram illustrating assembly instructions and safety warnings:

- Top Warning:** A warning triangle with an exclamation mark is connected to a box containing:
  - A circle showing an Allen key and a bolt.
  - A crossed-out power drill.
- Time:** A clock icon with the text "60'" below it, indicating a 60-minute assembly time.
- Bottom Warning:** A warning triangle with an exclamation mark is connected to a box containing:
  - A circle showing a rectangular block being placed on a textured surface.
  - A crossed-out diagram of a block being placed on a smooth surface.
- Person Icon:** A stick figure icon with the number "2" below it, indicating that two people are required for assembly.




<p>1</p>  <p>x 2</p>	<p>2</p>  <p>x 2</p>	<p>3</p>  <p>x 1</p>	<p>4</p>  <p>x 1</p>	<p>5</p>  <p>x 8</p>
---	---	---	--	---

A



x 8

B




x 8

C




x 4

D




x 4

E




x 1

F






x 1

G






x 4

1




2



3

G



x 4

C





x 4

F




x 1





4

5



x 8



!

