
Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts which may have come loose inside the carton during shipment. Separate, identify and count all parts and hardware. Compare with the parts list to be sure all parts are present. "DO NOT TIGHTEN SCREWS UNTIL COMPLETELY ASSEMBLED"

IMPORTANT: PLEASE READ INSTRUCTION BEFORE STARTING THE ASSEMBLY

Finish








Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts which may have come loose inside the carton during shipment. Separate, identify and count all parts and hardware. Compare with the parts list to be sure all parts are present. "DO NOT TIGHTEN SCREWS UNTIL COMPLETELY ASSEMBLED"

IMPORTANT: PLEASE READ INSTRUCTION BEFORE STARTING THE ASSEMBLY


Finish



Hardware List

NO.	Description	Drawing	Size	Q'ty
1	Flat Head Bolt		Ø1/4"x38mm	8
2	Flat Washer	0	Ø1/4"x19x2mm	8
3	Spring Washer	0	Ø1/4"	8
4	Allen Key		4mm	1

Step 1



Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts which may have come loose inside the carton during shipment. Separate, identify and count all parts and hardware. Compare with the parts list to be sure all parts are present. "DO NOT TIGHTEN SCREWS UNTIL COMPLETELY ASSEMBLED"


IMPORTANT: PLEASE READ INSTRUCTION BEFORE STARTING THE ASSEMBLY

Finish Anti Tipping Hardware

Hardware List


NO.	Description	Drawing	Q'ty
Α	Tipping Restraint	9	1set





Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts which may have come loose inside the carton during shipment. Separate, identify and count all parts and hardware. Compare with the parts list to be sure all parts are present. "DO NOT TIGHTEN SCREWS UNTIL COMPLETELY ASSEMBLED"

IMPORTANT: PLEASE READ INSTRUCTION BEFORE STARTING THE ASSEMBLY



Hardware List

NO.	Description	Drawing	Q'ty
А	Tipping Restraint	9	1set

Step 1

