











Diagram illustrating assembly instructions and warnings:

- Warning 1:** A triangle with an exclamation mark points to a box containing an L-shaped bracket and a power drill with a slash through it, indicating that a power drill should not be used for this step.
- Warning 2:** A triangle with an exclamation mark points to a box containing a rectangular block being placed on a surface and another block being pushed down, indicating a specific assembly sequence.
- Time:** A clock icon is labeled "30'", indicating the estimated assembly time.
- Person:** An icon of a person is labeled "1", indicating that one person is required for assembly.



1

<p>1</p>  <p>x 1</p>	<p>2</p>  <p>x 4</p>	<p>A</p>  <p>M6 x 45 x 8</p>	<p>B</p>  <p>x 8</p>	<p>C</p>  <p>x 1</p>
---	---	---	---	---

