




Weighing package



Step 1: Connecting wire (self provided main line)



(Graph 2-3) Drawing of connecting of load cell



Step 2: install



PS: The direction of the arrow is the direction of the force

Step 3: Calibration (refer to the manual **Chapter 4** or video)