













Assembly Instructions

Sideboard





HARDWARE-1



HARDWARE-2


X21



Φ 6x12

(K)

X17




(L)

X14




(M)




(N)

X6



(O)

X3



12"


(P)

X2



(Q)

1



I



[x1]

J




[x20]

K




[x20]

2




(A)



[x32]


(D)




[x16]



3



(A)




[x8]

(E)



[x18]


(P)




[x3]



4



A



[x4]

B



[x12]


C



[x12]



5



B



[x16]


C



[x16]



6



B



[x16]


C



[x16]



7



G




[x12]


M



[x12]



8




E



[x12]



O




[x6]



9



A




[x12]

E



[x12]


P



[x3]



10



B



[x12]

C



[x12]


F




[x12]



11




L



[x16]

12




E





[x24]



13



14



Q

Q



[x2]

