



# Work bench with one drawer



1




- 1) M6x14 mm (x8)
- 2) M4x12 mm (x10)
- 3) M4x10 mm (x8)
- 4) M4x10 mm (x8)
- 5) (x4)
- 6) M6 (x7)
- 7) M4 (x18)
- 8) M6 (x7)
- 9) M4 (x18)
- 10) (x12)
- 11) (x1)
- 12) (x2)
- 13) (x1)


2



- A(x1)
- B(x1)
- C(x1)
- D(x1)
- E(x1)




3




- 21) 900 mm (x2)
- 22) 956 mm (x2)
- 23) (x1)
- 24) (x1)
- 25) (x1)
- 26) (x1)
- 27) (x1)
- 28) (x1)


4




5




6




7




8



13)




14)




15)


9



16)




17)



18)

10



11