






IMPORTANT, RETAIN FOR FUTURE REFERENCE: READ CAREFULLY

ASSEMBLY & INSTRUCTION MANUAL


PARTS




h x 1




i x 1




j x 1




k x 2



L x 2




M x 2




N x 1


HARDWARE




a x 4
M6*30




b x 10
M6*50
+1(spare)



c x 4
M6*65




d x 2
M6*72



e x 1
65mm




f x 16
Φ 20
+1(spare)




g x 4
M6


(b)		M6*50mm	10x
(f)		ø20mm	10x



(c)		M6*65mm	2x
(f)		ø20mm	2x
(g)		M6mm	2x



(c)		M6*65mm	2x
(d)		M6*72mm	2x
(f)		ø20mm	4x
(g)		M6mm	2x



(a)		M6*30mm	4x
-----	---	---------	----

