



















Assembly Instruction







 Hammer and Screwdriver
 are not included !!




| NO. | QTY. | LINEDRAWING |
|-----|------|---|
| (A) | 29 |  |
| (B) | 29 |  |
| (C) | 10 |  |
| (D) | 6 |  |
| (E) | 4 |  |
| (F) | 22 |  |
| (G) | 48 |  |
| (H) | 1 |  |
| (I) | 6 |  |
| (J) | 29 |  |
| (K) | 2 |  |
| (L) | 4 |  |
| (M) | 4 |  |
| (N) | 4 |  |
| (O) | 2 |  |





PARTS LIST




| NO. | QTY. |
|-----|------|
| ① | 1 |
| ② | 1 |
| ③ | 1 |
| ④ | 1 |
| ⑤ | 1 |
| ⑥ | 1 |
| ⑦ | 1 |
| ⑧ | 1 |
| ⑨ | 1 |
| ⑩ | 1 |
| ⑪ | 1 |
| ⑫ | 1 |
| ⑬ | 1 |
| ⑭ | 1 |
| ⑮ | 1 |
| ⑯ | 1 |
| ⑰ | 1 |
| ⑱ | 2 |
| ⑲ | 4 |





1




| | | | | | | | |
|---|--|---|--|---|--|---|--|
| H |  | G |  Ø3.5x14 | L |  | M |  |
| | 1x | | 4x | | 4x | | 4x |





2




| | | | |
|---|--|---|--|
| A |  | B |  |
| | 3x | | 3x |
| C |  | J |  |
| | 2x | | 3x |





3




| | | | |
|---|---|---|---|
| A |  | B |  |
| | 3x | | 3x |
| C |  | J |  |
| | 2x | | 3x |

4








| | | | |
|---|---|---|---|
| A |  | B |  |
| | 12x | | 12x |
| C |  | J |  |
| | 2x | | 12x |

5





6





| | | | |
|---|--|---|--|
| A |  | B |  |
| | 7x | | 7x |
| C |  | J |  |
| | 2x | | 7x |


7




8





| | |
|---|---|
| F |  |
| | 22x |


| | |
|---|---|
| I |  |
| | 6x |

9








| | |
|---|--|
| E | C |
|  Ø3.5x35 4x |  1x |
| 4x | 1x |

10






11




| | |
|---|---|
| A | B |
|  4x |  4x |
| 4x | 4x |
| C | J |
|  1x |  4x |
| 1x | 4x |



12




| | |
|---|--|
| H | G |
|  1x |  Ø3.5x14 4x |
| 1x | 4x |



13




| | | | |
|---|--|---|--|
| D |  | G |  Ø3.5x14 |
| | 2x | | 4x |


14




| | | | |
|---|--|---|--|
| K |  | G |  Ø3.5x14 |
| | 2x | | 12x |


15



| | |
|---|---|
| G |  Ø3.5x14 |
| | 4x |


16



| | |
|---|---|
| G |  Ø3.5x14 |
| | 4x |


17

X2




| | |
|----|----|
| D | G |
| 4x | 8x |

19



| | |
|---|----|
| 0 | 2x |
|---|----|

18



| | |
|----|----|
| N | G |
| 4x | 8x |