









Diagram showing a warning symbol (triangle with exclamation mark) above a box containing an L-shaped metal bracket and a crossed-out power drill. To the right is a clock icon with the text "15'" below it.

Diagram showing a warning symbol (triangle with exclamation mark) above a box containing a rectangular block on a textured surface and a crossed-out block with a downward arrow. To the right is a person icon with the text "1" below it.



1

<p>1</p>  <p>x 1</p>	<p>2</p>  <p>x 4</p>	<p>A</p>  <p>M8 x 30</p> <p>x 12</p>	<p>B</p>  <p>x 12</p>	<p>C</p>  <p>x 1</p>
---	---	---	--	---

