





ASSEMBLY INSTRUCTION


70% do not need to be tightened




3. 100% fully tightened




X1




X2



X2




X1



X4



X4



X8