



Ax1




Bx1



Cx2



Dx2



Ex2



Fx4



Gx20



Hx4




Ix4




Jx4
M3.5x $\frac{30}{1.2}$



Kx24
M3.5x $\frac{15}{0.6}$



Lx22



Mx2



Nx4




Ox4




Px2



Qx2



Rx4



Sx2



Tx2






Ux1



mm
inch


x2

①



②


Ox4



a

③


Gx8



b

④

Gx8





⑤




Nx4




Ux1



⑥




⑦




8



Lx22





9



10 x2



11




12

lx4




Qx2







x2

Qx1

lx2





13





14

Kx8 
M3.5x $\frac{15}{0.6}$







15

Tx2 
Mx2 



16

Px2



17

