


ASSEMBLY INSTRUCTIONS INSTRUCCIONES

4904BK/ 4904WH SIDE TABLE 4904BK/ 4904WH MESA LATERAL


PARTS LIST

NO.	DESCRIPTION	SKETCH	Q'TY
A	TABLE TOP		1
B	MOUNTING PLATE		1
C	UPPER PEDESTAL BASE		1
D	BOTTOM LEG		4
E	LOWER PEDESTAL BASE		1

HARDWARE LIST

NO.	DRAWING	DESCRIPTION	Q'TY
1	Bolt Ø1/4"-20x1-1/8"L		2
2	Bolt Ø1/4"-20x1-1/8"L		4
3	Allen key		1

STEP/PASO 1:



PAGE 1 OF 2


DO NOT TIGHTEN ALL BOLTS UNTIL COMPLETELY ASSEMBLED.

NO APRETAR LOS TORNILLOS HASTA ARMAR COMPLETAMENTE.


NOTE: PERIODICALLY CHECK TO ENSURE THAT ALL CONNECTORS (BOLTS, SCREWS, ETC.) ARE TIGHT.

NOTA: VERIFIQUE PERIÓDICAMENTE QUE TODOS LOS CONECTORES (TUERCAS, TORNILLOS, ETC.) ESTÉN BIEN APRETADOS


STEP/PASO 2:



STEP/PASO 3:




STEP/PASO 4:



STEP/PASO 5:

Complete.



DO NOT TIGHTEN ALL BOLTS UNTIL COMPLETELY ASSEMBLED.
NO APRETAR LOS TORNILLOS HASTA ARMAR COMPLETAMENTE.
NOTE: PERIODICALLY CHECK TO ENSURE THAT ALL CONNECTORS (BOLTS, SCREWS, ETC.) ARE TIGHT.
NOTA: VERIFIQUE PERIÓDICAMENTE QUE TODOS LOS CONECTORES (TUERCAS, TORNILLOS, ETC.) ESTÉN BIEN APRETADOS