






















Xilingol



CAUTION:When tightening the screws, tighten sequentially. Do not tighten any screws fully and then towards the next one. When every part is OK, then tighten all the screws.

NFN014




①  1PC	②  1PC	③  1PC	④  1PC
⑤  1PC	⑥  1PC	⑦  2PCS	⑧  1PC
⑨  2PCS	⑩  2PCS	⑪  1PC	⑫  1PC
⑬  1PC	⑭  1PC	⑮  1PC	⑯  1PC
⑰  1PC	⑱  1PC	⑲  1PC	⑳  1PC


A×30 +1



B×1



C×1



D×18 +1



E×20 +1




F×30 +1



G×8 +1



H×4 +1



I×17 +1



J×14 +1



K×2



L×1



M×2



N×1




O×4 +1




P×1




Q×1



R×1




S×1



T×1




1




A×4



B×1




C×1



D×4



2




E×2



F×2





3





E×2	F×2
	
φ6×30mm	φ15×10mm

4



A×4	F×6	G×4
		
φ6×35mm	φ15×10mm	φ8×30mm

5



A x 8

 $\phi 6 \times 35\text{mm}$


G x 4

 $\phi 8 \times 30\text{mm}$


H x 4

 $\phi 4 \times 35\text{mm}$


6



x 2



A x 4

 $\phi 6 \times 35\text{mm}$



E x 4

 $\phi 6 \times 30\text{mm}$

F x 4

 $\phi 15 \times 10\text{mm}$

7






E x 4

$\phi 6 \times 30\text{mm}$



F x 8

$\phi 15 \times 10\text{mm}$



8




9




10




11



12



13



N×1




0×2



Ø4×14mm

14




D×4



Ø3×12mm


15



0x2

 $\phi 4 \times 14\text{mm}$

16



A x 4

F x 4



A x 4

 $\phi 6 \times 35\text{mm}$

F x 4



 $\phi 15 \times 10\text{mm}$



17




J×4	P×1	Q×1
		
φ4×30mm		φ4×8mm

18



D×6	R×1	S×1
		
φ3×12mm		

19



20

